The Openport 2.0 J2534 DLL has debugging options which are settable via an IOCTL call that provide debug output for every subsequent J2534 call that is made. You can turn this debugging on by making the following J2534 call:

```
#include "j2534 tactrix.h"
#include "j2534.h"
// the following are defined in the above header
// #define TX IOCTL BASE
                                        0x70000
// #define TX IOCTL SET DLL DEBUG FLAGS
                                                   (TX IOCTL BASE+1)
// #define TX IOCTL DLL DEBUG FLAG J2534 CALLS
                                                                 0x0000001
void main()
  J2534 j2534;
  i2534.init();
  unsigned int flags = TX IOCTL DLL DEBUG FLAG J2534 CALLS;
  j2534.PassThruloctl(0,TX IOCTL SET DLL DEBUG FLAGS,(void*)flags,NULL);
  // now use the J2534 DLL as you wish (open, connect, etc.)
}
```

Once the debugging is turned on, you can capture the output in any Windows debugger or dbgview. Notice that this call can be made as soon as the DLL is loaded, before connecting to any device, allowing you to log even the opening and closing of the device. Keep in mind that the debug output can significantly slow the throughput of the DLL - do not leave the debugging on all of the time.